# Oil Field Environmental Incident Summary

Responsible Party: SUSPECTED VANDALISM ON CLR LOCATION

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: FREDDY 1-8H

Field Name: SADLER Well File #: 19966

Date Incident:12/21/2014Time Incident:08:00Facility ID Number:County:DIVIDETwp:161Rng:95Sec:8Qtr:

Location Description:

Submitted By: Patrick Skillestad Received By:

Contact Person: Patrick Skillestad

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 200 Barrels 200 Barrels 200 barrels

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 10/14/2016 Clean Up Concluded: 12/22/2014

Risk Evaluation:

None

Areal Extent:

3 ft x 50 ft

## Potential Environmental Impacts:

Location soil

### Action Taken or Planned:

Standing fluid was sucked up taken to another CLR disposal. Contaminated soil will be removed and disposed of.

Wastes Disposal Location: Fluids to Lloyd SWD and solids to Prairie Disposal.

Agencies Involved:

#### **Updates**

Date: 12/22/2014 Status: Reviewed - Assigned to Other Agency Author: Martin, Russell

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

Release, due to valve/piping connection leak, remained on location within the diking according to the report. NDIC retains oversight.